

YS-SSD01/02/03


拉布裁剪设备

Cutting table series

导带(分段)式自动输送桌



■ 输送流程



■ 规格 / SPECIFICATION

	常规款(型号PA-SSD-01)	PLC触控+伺服电机款(型号PA-SSD-02)	型号PA-SSD-03
滚筒、托辊 Roller, roller	参照样品或已装	Reference or loading of samples	在YS-SSD-02型号基础上， 强化硬件设备，符合高端公 司客户的安全生产管理化标准。 Based on the YS-SSD-02 model, the hardware equipment is strengthened to meet the safety production management standards of high-end customers.
台板、塑面 Table plate, plastic surface	参照样品或已装	Reference or loading of samples	
PVC输送带 PVC conveyor belt	<ul style="list-style-type: none"> 标配深灰色哑光色 1830宽板面配1580宽输送带 2130宽板面配1880宽输送带 2330宽板面配2080宽输送带 颜色尺寸都可定制，需提前说明 	<ul style="list-style-type: none"> Standard dark grey matte 1830 wide plate surface with 1580 wide conveyor belt 2130 wide plate surface with 1880 wide conveyor belt 2330 wide plate surface with 2080 wide conveyor belt Color and size can be customized, please specify in advance 	
脚架 Scaffolding	国标螺丝螺帽等五金件 National standard hardware such as screws and nuts 人工打磨(非硫酸浸泡) Manual grinding (non-sulfuric acid immersion) 粉末漆高温烘干防腐蚀 Baking powder paint at high temperature to prevent corrosion	国标螺丝螺帽等五金件 National standard hardware such as screws and nuts 人工打磨(非硫酸浸泡) Manual grinding (non-sulfuric acid immersion) 粉末漆高温烘干防腐蚀 High temperature baking powder paint anti-corrosion color customized 粉末漆高温烘干防腐蚀颜色定制	
不锈钢包边 Stainless steel edge wrapping	标配样品品质宽度，尺寸要求需提前说明 Standard sample quality width, dimension requirements need to be specified in advance		
电机 Motor	专用品牌常规电机 Special brand conventional motor		
软件系统 Software system	参照样品或已装 Reference or loading of samples		
操作系统 Operating system	按钮式操作进退 Push button operation forward and backward	触控屏(前进后退联动、微调速度等) Touch screen (forward and backward linkage, fine-tuning speed, etc.)	
无线对接机床系统 Wireless docking machine bed system	参照样品或已装 Reference or loading of samples		

对比传统浮桌板 Contrast traditional floating table board

气浮桌 Air floatation table	导带(分段)式自动输送桌 Guide belt (section) automatic conveyor table	
使用人工拉送面(皮料), 难以保证垂直状态送至自动裁床, 影响精度 Using manual drawing surface (skin) material, it is difficult to ensure that the vertical state is sent to the automatic cutting bed, which affects the accuracy.	从自动铺布机至自动裁床全称垂直运输 Vertical transportation from automatic laying machine to automatic bed cutting	精确运输 Precise transportation
依靠裁床的吸力强行拉动, 易使部分面料拉伸影响精度 Depending on the suction of the cutting bed, it is easy to influence the tensile accuracy of some fabrics.	与裁床频率同步输送, 配合高端裁床边走边裁 Synchronous transmission with the frequency of the cutting bed, with the high-end cutting bed while walking and cutting	高配合度 High coordination degree
使用全程开启风机, 耗电大 Use the whole process to turn on the fan and consume a lot of electricity	输送时才使用电量, 耗电不足气浮桌的1/10 To consume electricity only when it is transported, and consume less than 1 / 10 of the air floatation table.	低能耗电 Low energy consumption electricity
需两人拉送 It takes two to pull.	可分段控制成联动控制, 操控裁床的技工即可按键完成 It can be controlled into linkage control, and the mechanic who controls the cutting bed can press the button to complete it.	省时省力 Save time and effort