

MC-17

弧形热压机

Pneumatic Curve Press Machine



特性 / Description:

- 1、弧型发热模具，适合各种弧弯部位压合
- 2、脚踏式随意张紧装置，操作更高效
- 3、悬空式下柱设计更适合袖口、裤脚成品压合
- 4、PLC控制温度、时间

- 1、Curve heating platform, suitable for many small curve position in heat bonding.
- 2、Foot pedal to adjust the tension, make operation more efficiency.
- 3、Suitable for cuff or leg position in heat bonding.
- 4、PLC programmable logic control system for temperature and time.

技术参数 / Specifications:

电压 : AC 220V 50/60Hz	Power Supply : AC 220V 50/60Hz
气压 : 0.3-0.5MPa	Air Pressure : 0.3-0.5MPa
功率 : 700W	Power Consumption : 700W
最高设定温度 : 250°C	Max. Setting Temp. : 250°C
加压时间 : 1-999s	Press Time : 1-999s
发热板面积 : R40*70mm	Heating Plate Area : R40*70mm
外型尺寸 : 1000(L)*500(W)*1750(H)mm	Dimension : 1000(L)*500(W)*1750(H)mm
净重 : 45kg	Net Weight : 45kg

