

## MC-18

### 弧形热压机

#### Pneumatic Curve Press Machine



#### 特性 / Description:

- 1、上发热体及下底座3D特效设计，保证上下弧度完全吻合压力一致均匀。
- 2、可选购下吸风模具。
- 3、标配大，中，小，下工作台模具，可轻松更换。
- 4、安全杆保护装置，安全生产有保证。
- 5、PLC控制系统，确保温度平均精准。

- 1、3D design for upper curve heating mold & lower platform, make the pressure evenly distribute in heat bonding for many small curve position
- 2、Vacuum suction lower platform is available
- 3、Flexible changeable standard 3 size lower platform, make it suitable for different processing
- 4、Reliable safety lever device operate more safety
- 5、PLC programmable logic control system for temperature and time

#### 技术参数 / Specifications:

电压: AC 220V 50/60Hz	Power Supply : AC 220V 50/60Hz
气压: > 0.4 MPa	Air Pressure : > 0.4 MPa
功率: 2400W	Power Consumption :2400W
最高设定温度: 250°C	Max. Setting Temp. : 250°C
加压时间: 1-999s	Press Time : 1-999s
发热板面积: 300(R190mm)*75mm	Heating Plate Area :300(R190mm)*75mm
外型尺寸: 450(L)*450(W)*1300(H)mm	Dimension : 450(L)*450(W)*1300(H)mm
净重:59kg	Net Weight :59Kg

